

Annex 3

Google view of site, 2008 (looking north)



**Annex 4a**

Raising the ground levels historic rubble dumping at Paradise Farm (April 1996)




**Annex 4b**

Raising the ground -- historic soil dumping at Paradise Farm (2003/2004)



**Annex 5**





Also area now plot 1. We think it is quite likely the land is contaminated from the dumped rubbish and possibly asbestos amongst the rubble?



Clearly plot 1 as you can see the position of the sewer pipes.

Annex 6

1980s view looking south-east from number 17, showing flooding and true level of banks



Annex 7

View from The Causeway, south of site. Compare with Annex 3 (March 2011)

